

Data

ID number	CALL_TIME	REVISED_IF	description
1	03/12/2021 23:01	FDR	derelict motorcycle on construction site
2	21/04/2021 13:07	FDR	welfare shipping container on construction site
3	20/07/2019 12:45	FDR	chapel building under construction
4	17/06/2019 09:32	FDR	Tyres manufacturer with roofing construction occurring
5	12/11/2017 13:33	FDR	Terraced house under construction
6	21/03/2022 14:39	SEC	Bonfire on construction site - advice given to extinguish
7	02/07/2021 20:45	SEC	Loose refuse/rubbish on construction site
8	27/01/2021 16:46	SEC	Large amount of timber alight on construction site
9	23/08/2019 20:53	SEC	Pallets on fire behind new building construction site
10	15/07/2019 17:49	SEC	Loose refuse/rubbish on construction site
11	11/04/2019 10:33	SEC	polystyrene on construction site
12	29/11/2017 16:35	SEC	bonfire at house under construction

Cause
heat source brought together deliberately
overheating
careless handling of smoking materials
Bitumen and roofing material ignited by hot work by roofing contractors
deliberate ignition of newspaper and waste
Bonfire
Deliberate burning
accidental
deliberate
deliberate
accidental - discarded cigarette
accidental